



Parametric hole finishing.



TheMagicUnicorn

[VIEW IN BROWSER](#)

updated 28. 11. 2023 | published 28. 11. 2023

Summary

To achieve a perfect finish when creating a hole to pass your filament or any other wire through the other side.

[3D Printers](#) > [Accessories](#)


Tags: [parametric](#) [design](#) [holecover](#) [finishing](#)
[parametricdesign](#)

For the parametric file, Always keep a minimum of 4mm between Width and HoleWidth parameter

Do not hesitate to send me a message if you have any problem with the model.

Enjoy !

Model files



parametric-filament-passage.f3d

☐ Keep a minimum of 4mm between Width and HoleWidth parameter



8mm-outerdiameter-17mm-depth-33mm-innerdiameter.stl



35mm-outerwidth-10mm-outerheight-17mm-depth-4mm-inn... .stl



10mm-outerdiameter-17mm-depth-4mm-innerdiameter.stl

License ©

This work is licensed under a
[Creative Commons \(4.0 International License\)](#)



Attribution—Noncommercial—Share Alike

- ✗ | Sharing without ATTRIBUTION
- ✓ | Remix Culture allowed
- ✗ | Commercial Use
- ✗ | Free Cultural Works
- ✗ | Meets Open Definition