



QIDI X-Max3 Wall Mounted Dry Box



Kavelry3D

[VIEW IN BROWSER](#)

updated 1. 1. 2024 | published 1. 1. 2024

Summary


Keep Your Filament Dry and Accessible

[3D Printers](#) > [Other Printer Parts & Upgrades](#)

Tags: qidi xmax3

This mod requires soldering and putting holes in your walls and modifying your dry box, but will allow you to relocate the filament run out sensor to the top of the printer and mount the dry box to the wall.

Model files



[wall-mounted-dry-box.step](#)




[wall-mounted-dry-box-base.stl](#)



wall-mounted-dry-box-top.stl



dry-box-spout.stl



filament-run-out-sensor-mount.stl

License ©

This work is licensed under a
[BSD License](#)



- ✗ | Sharing without ATTRIBUTION
- ✓ | Remix Culture allowed
- ✓ | Commercial Use
- ✓ | Free Cultural Works
- ✓ | Meets Open Definition