



5 Minute Z Calibration Surface / First Layer Calibration



Nils Kal

[VIEW IN BROWSER](#)

updated 17. 2. 2020 | published 9. 2. 2020

Summary

Yet another first layer calibration surface. Use it to get your Z level for the first layer right. Ooze free gcode!



0.08 hrs



1 pcs



0.20 mm



0.40 mm



PLA




1 g



Prusa
MK3/S/S+

[3D Printers](#) > [Test Models](#)

Tags: [prusa](#) [mk3](#) [printer](#) [i3](#) [calibration](#) [mk3s](#) [first](#)
[level](#) [bed](#) [z](#) [layer](#) [surface](#)



Yet another first layer calibration surface.

Use it to get your Z level for the first layer right.

Ooze free gcode!

Model files



z-calibration.stl

Print files



z-calibration_02mm_pla_mk3s_5m.gcode

🌀 PLA 📏 0.40 mm 📏 0.20 mm ⌚ 0.08 hrs 📊 1 g 🖨️ Prusa MK3/S/S+

License ©



This work is licensed under a
[Creative Commons \(4.0 International License\)](#)

Attribution-NonCommercial

-
- ✗ | Sharing without ATTRIBUTION
 - ✓ | Remix Culture allowed
 - ✗ | Commercial Use
 - ✗ | Free Cultural Works
 - ✗ | Meets Open Definition