



Root 3 CNC Box Section Linear guide Remix



kjoh

[VIEW IN BROWSER](#)

updated 12. 4. 2022 | published 12. 2. 2022

Summary

Added hubs to the holes where the bearings sit, eliminating the need for washers. Same concept as used on the Y Gantry...

[Hobby & Makers](#) > [Tools](#)

Added hubs to the holes where the bearings sit, eliminating the need for washers. Same concept as used on the Y Gantry Bearing Cap and other parts.

Print Settings

Printer Brand:

Prusa

Printer:

Prusa Clone

Rafts:

No

Supports:

No

Resolution:

0.3

Infill:

30%

Category: DIY

Model files



box_section_linear_guide_washer.stl

Other files



sources.txt

[Find source .stl files on Thingiverse.com](#)

License

This work is licensed under a
Creative Commons (4.0 International License)



Attribution

-
- ✗ | Sharing without ATTRIBUTION
 - ✓ | Remix Culture allowed
 - ✓ | Commercial Use
 - ✓ | Free Cultural Works
 - ✓ | Meets Open Definition

