



## Joe Blow Sports Floor Pump Leakage Fix

j joergp

[VIEW IN BROWSER](#)

updated 16. 2. 2022 | published 16. 2. 2022

### Summary

Plug for sealing the Schrader side of the pump head. Fixed a leakage on my pump.

[Sports & Outdoor](#) > [Outdoor Sports](#)


Tags: [topeak](#) [bicycle](#) [pump](#) [bike](#)

My Joe Blow Sports floor pump leaked air at the Schrader side of the pump head. The Topeak Rebuild Kit did not fix this issue.

I created this simple plug that seals the Schrader side, which works just fine. Don't use, if you need to use the pump with Schrader type valves.

BTW: a simple sealing disc would have done the job, too ;-)

### Model files



joe-blow\_fix.scad



joe-blow\_fix.stl

## License ©

This work is licensed under a  
**Creative Commons (4.0 International License)**



**Attribution—Noncommercial—Share Alike**

---

- ✗ | Sharing without ATTRIBUTION
- ✓ | Remix Culture allowed
- ✗ | Commercial Use
- ✗ | Free Cultural Works
- ✗ | Meets Open Definition