



Sensor ball replacement

 **Juan Conde**

[VIEW IN BROWSER](#)

updated 21. 3. 2022 | published 21. 3. 2022

Summary

The filament sensor never work as is supposed to do. Replace the iron ball with this mod never fail again.

[3D Printers](#) > [3D Printers - Upgrades](#)

Tags: [filament](#) [sensor](#) [filamentsensor](#)

Model files



bola-sensor-filamento-2.stl

License

This work is licensed under a
Creative Commons (International License)



Public Domain

- ✓ | Sharing without ATTRIBUTION
- ✓ | Remix Culture allowed
- ✓ | Commercial Use
- ✓ | Free Cultural Works
- ✓ | Meets Open Definition