



Kenwood AT282 Fix

t **tunisiano187**

[VIEW IN BROWSER](#)

updated 22. 3. 2022 | published 22. 3. 2022

Summary

This thing can repair the bottom piece of a Kenwood Blender AT282



0.73 hrs



1 pcs



0.15 mm



0.40 mm



PLA



3 g



Prusa
MK3/S/S+

[Household](#) > [Kitchen](#)

Aucun support nécessaire

Pièce de réparation d'un blender Kenwood AT282

imprimé en PLA avec un Infill de 15%

Model files



blender_v4.stl

Print files



blender_v4_015mm_pla_mk3s_44m.gcode

🌀 PLA 🌀 0.40 mm 🌀 0.15 mm 🕒 0.73 hrs 📊 3 g 🖨️ Prusa MK3/S/S+

License ©



This work is licensed under a
[Creative Commons \(4.0 International License\)](#)

Attribution-NonCommercial

-
- ✗ | Sharing without ATTRIBUTION
 - ✓ | Remix Culture allowed
 - ✗ | Commercial Use
 - ✗ | Free Cultural Works
 - ✗ | Meets Open Definition