



Cricut Maker Roller fix

m mjf55

[VIEW IN BROWSER](#)

updated 24. 3. 2022 | published 24. 3. 2022

Summary

After some usage, the Cricut Maker roller has been known to move on the rod causing cut fails.

[Hobby & Makers](#) > [Other Ideas](#)

Tags: [roller](#) [cricutmaker](#)

The Cricut Maker has had a problem (on some units) where the roller on the paper hold down bar will migrate off the edge of the cutting mat. This will cause the cut to fail. The details are in the reddit link below. The net of it is that a McMaster - Carr clip was identified as a fix / workaround. While the metal clip is a good solution, I used the McMaster-Carr design file and made it an stl. You can use this to get back in operation while you order a part.

Not much done here except to make the stl available for someone with this issue to get back cutting.

Model files



98808a350_low-clearance-external-retaining-ring.stl

[Find source .stl files on Thingiverse.com](#)

License ©

This work is licensed under a
Creative Commons (4.0 International License)



Attribution-NonCommercial

-
- ✗ | Sharing without ATTRIBUTION
 - ✓ | Remix Culture allowed
 - ✗ | Commercial Use
 - ✗ | Free Cultural Works
 - ✗ | Meets Open Definition