



IEC - 40x40 extrusion mount



AcerMaker88

[VIEW IN BROWSER](#)

updated 16. 5. 2022 | published 16. 5. 2022

Summary

After installing my AC hea

[3D Printers](#) > [Accessories](#)

Tags: power

After installing my AC heated bed, i wanted to seperate the power source away from my printer power supply. I used this mount and an IEC with fuse to have a seperate power source.

Designed this to attach to a 40x40 extrusion frame

IEC i used - https://www.amazon.com/dp/B082ZFRV1B?ref_cm_sw_r_cp_ud_dp_VRHW48ABDNBR43B7VVG9

PLA - 25%

Supports Required - Touching Build Plate Only

Model files



iec_mount.stl

License

This work is licensed under a
[Creative Commons \(4.0 International License\)](#)



Attribution

- ✗ | Sharing without ATTRIBUTION
- ✓ | Remix Culture allowed
- ✓ | Commercial Use
- ✓ | Free Cultural Works
- ✓ | Meets Open Definition