



CCTREE spool fix for Bambu AMS



Jaco van Zweel

[VIEW IN BROWSER](#)

updated 28. 11. 2022 | published 28. 11. 2022

Summary


Clip to close the notches in CCTREE spools

[3D Printers](#) > [Accessories](#)

Tags: [spool](#) [filament](#) [notch](#) [fix](#) [bambu](#) [ams](#) [cctree](#)

The CCTREE spools I have, have notches in them. These notches catch on the Bambu AMS feeder rollers, causing feed errors. At worst, I believe this could lead to damage to the AMS. So, these clip in place clips are designed to fill the notches, ensuring a smooth roll off the spool over the feeder rollers in the Bambu AMS.

Model files



cctree-clip.3mf

License

This work is licensed under a
Creative Commons (4.0 International License)



Attribution-NonCommercial

- ✗ | Sharing without ATTRIBUTION
- ✓ | Remix Culture allowed
- ✗ | Commercial Use
- ✗ | Free Cultural Works
- ✗ | Meets Open Definition