



## Burnout test for castable resins & colorless natural PLA



Cat3D

[VIEW IN BROWSER](#)

updated 25. 2. 2023 | published 25. 2. 2023

### Summary

This is a sample I have created in order to test how castable resins will burn out.

[Hobby & Makers](#) > [Other Ideas](#)

Tags: [burn](#) [casting](#) [metalcasting](#) [burnout](#)

This is a sample I have created in order to test how castable resins will burn out.

I have already recorded a teaser video about the series I want to create.

<https://youtu.be/9bUism1AtC8>

Some pictures of the samples will follow.

The idea is to find a material with good burnout behavior and a clean burn out without leaving ashes behind.

### Print instructions

For PLA I have printed them in 100% size and for castable resins in 75% in order to save resin. As you might know most of them are really expensive! 0.2mm layer height and 100% infill

For resin 50 micron would just be fine. Locate it flat on the build surface for faster printing time

# Model files



burnout-test.stl

## License



This work is licensed under a  
[Creative Commons \(4.0 International License\)](https://creativecommons.org/licenses/by-nc-sa/4.0/)

**Attribution—Noncommercial—Share Alike**

- 
- ✗ | Sharing without ATTRIBUTION
  - ✓ | Remix Culture allowed
  - ✗ | Commercial Use
  - ✗ | Free Cultural Works
  - ✗ | Meets Open Definition