



iRobot Roomba S9+ dock fix



Dot Dot Dash

[VIEW IN BROWSER](#)

updated 31. 7. 2023 | published 31. 7. 2023

Summary

fix for easy to break bag tube tab on Roomba dock.



0.76 hrs



1 pcs



0.15 mm



0.40 mm



PET



5 g



Prusa
MK3/S/S+

[Gadgets](#) > [Other Gadgets](#)

Tags: [s9](#) [s9plus](#) [irobot](#) [roomba](#)

Got a Roomba s9+ with the tab that moves the bag tube broken. You can not purchase this part and finding a used replacement is VERY hard, SO I designed this two piece fix for the tube tab. printed in PETG with 100% infill 4 perimeters and glued on to the part after removing the remaining tab structure.

Model files

roomba-tube-fix-v1.3mf



Print files

body1_04n_015mm_petg_mk3s_46m.gcode



PET 0.40 mm 0.15 mm 0.76 hrs 5 g Prusa MK3/S/S+

License ©

This work is licensed under a
[Creative Commons \(4.0 International License\)](#)



Attribution—Noncommercial—Share Alike

-
- ✗ | Sharing without ATTRIBUTION
 - ✓ | Remix Culture allowed
 - ✗ | Commercial Use
 - ✗ | Free Cultural Works
 - ✗ | Meets Open Definition