



Airsoft Fast Loader Handle



hamolicious

[VIEW IN BROWSER](#)

updated 2. 8. 2023 | published 2. 8. 2023

Summary

Airsoft Fast Loader's Handle, I lost mine a while back and only just decided to make a replacement.

[Hobby & Makers](#) > [Tools](#)

Tags: [airsoft](#) [speedloader](#) [fastloader](#)

Requires an M3x8 or M3x6 brass thread insert and an M3x16 screw, push the insert in and thread the screw in through the handle on the loader and your 3D printed handle and screw in until tight, this should leave some play between the 3D printed handle and the speed-loader's handle which will allow the 3D printed handle to spin as you twist.

I also used a smidge of super glue on the insert to ensure it won't go anywhere.

Model files



just-screw.3mf

☐ no brass insert needed



brass-insert.3mf



sidewinderhandle.step

☐ for your modding needs :)



sidewinderhandle.f3d

☐ for your modding needs :)

License ©

This work is licensed under a
Creative Commons (International License)



Public Domain

-
- ✓ | Sharing without ATTRIBUTION
 - ✓ | Remix Culture allowed
 - ✓ | Commercial Use
 - ✓ | Free Cultural Works
 - ✓ | Meets Open Definition