

Printables logo

PTFE Connector Support - X/P Series

3D MODEL
ONLY

[AneoPsy AneoPsy](#)

[View in browser](#)

updated 20. 2. 2024 | published 20. 2. 2024

Summary

PTFE Connector Support

[3D Printers](#) > [Bambu Lab Parts & Upgrades](#)

Tags: [support](#) [ptfe](#) [tube](#) [connector](#) [ptfetubeorganizer](#) [help](#) [error](#) [ams](#)

PTFE Connector Support

The **PTFE Connector Support** corrects certain AMS failures, such as filament feed failures and retraction failures, by reducing the resistance created at the entry of the PTFE connector on the back of your X1C or P1P/P1S.

INSTRUCTIONS:

1. Remove the PTFE tube from the **BLACK** side of the connector.
2. Insert the PTFE tube into the 3D model from the small hole side.
3. Once the tube is fully inserted into the PTFE connector, push the 3D model around the PTFE connector.

BENEFITS:

- Fast to print
- Easy to use
- Small & Strong
- Designed for FDM Printing
- Smooth Operation

Model files

ptfe-connector-support.3mf

License ©

This work is licensed under a
[Creative Commons \(4.0 International License\)](https://creativecommons.org/licenses/by-nc-nd/4.0/)



[Attribution—Noncommercial—No Derivatives](https://creativecommons.org/licenses/by-nc-nd/4.0/)

-
- ✗ | Sharing without ATTRIBUTION
 - ✗ | Remix Culture allowed
 - ✗ | Commercial Use
 - ✗ | Free Cultural Works
 - ✗ | Meets Open Definition