

KP3S X_axis simple tensioner

 Hanz_Grau

[VIEW IN BROWSER](#)

updated 16. 1. 2024 | published 16. 1. 2024

Summary

Material: 2pcs - set screw M3x12 1pcs - set screw M4x12 This is very simple, but useful X axis belt tensioner. M4 set...

[3D Printers](#) > [Other Printer Parts & Upgrades](#)

Tags: [tensioner](#) [thingiverse](#) [kp3s](#)

Material:

2pcs - set screw M3x12

1pcs - set screw M4x12

This is very simple, but useful X axis belt tensioner.

M4 set screw is used for main tension setting. M3 screws are supports for prevent wobbling.

OnShape: <https://cad.onshape.com/documents/abed3ef82c52b44b513ec893/w/ed98172a7039528454403fc0/e/6f3b75510278bad569a71ea0>

Print Settings

Printer Brand:

Kingroon

Printer:

Kingroon KP3S

Rafts:

No

Supports:

No

Resolution:

0.2


Infill:

60%

Filament: Aurapol PLA

Category: 3D Printer Parts

Model files



x_tensioner.stl

[Find source .stl files on Thingiverse.com](#)

License ©

This work is licensed under a
[Creative Commons \(4.0 International License\)](#)



Attribution

- ✖ | Sharing without ATTRIBUTION
- ✔ | Remix Culture allowed
- ✔ | Commercial Use
- ✔ | Free Cultural Works
- ✔ | Meets Open Definition