



Ender 3 V2 Z stepper mount



Peter

[VIEW IN BROWSER](#)

updated 19. 1. 2024 | published 19. 1. 2024

Summary

X-Y direction positionable mount

[3D Printers](#) > [Creality Parts & Upgrades](#)

Tags: [ender3](#) [ender3v2](#) [steppermount](#)

During my fight with Z banding i made this mount, i like the more degree freedom of proper alignment of mechanics. You can adjut the stepper motor in Y and the mount itself in X direction.

For motor fastening you need 4 pices M3X10 screw, for the mount 4 pices M4X10 screw. (washers, hammerhead nuts)

Printable without support.

I rotated the motor 90°, the connector looks sideways.

Model files



stepper-mount.stl

License



This work is licensed under a
[Creative Commons \(4.0 International License\)](https://creativecommons.org/licenses/by-nc-sa/4.0/)

Attribution—Noncommercial—Share Alike

-
- ✗ | Sharing without ATTRIBUTION
 - ✓ | Remix Culture allowed
 - ✗ | Commercial Use
 - ✗ | Free Cultural Works
 - ✗ | Meets Open Definition