



DELL OptiPlex 7780 AIO camera fix

 **Releud**

[VIEW IN BROWSER](#)

updated 19. 5. 2024 | published 19. 5. 2024

Summary

When my Optiplex 7780 heated up under load, the camera often popped out spontaneously. This part solved the problem.

[Gadgets](#) > [Computers](#)

I printed from PETG with a layer of 0.12 mm, infill 80%.

Model files



7780-camera-fix.stl

License

This work is licensed under a
[Creative Commons \(4.0 International License\)](#)



Attribution-NonCommercial

- ✗ | Sharing without ATTRIBUTION
- ✓ | Remix Culture allowed
- ✗ | Commercial Use
- ✗ | Free Cultural Works
- ✗ | Meets Open Definition