



LatheTail Stock String Steady Rest

A Alan Stratton

VIEW IN BROWSER

updated 20. 6. 2024 | published 20. 6. 2024

Summary

When turning long very thin, a string steady rest mounted to the tail stock is essential.

[Hobby & Makers](#) > [Tools](#)

Tags: [string](#) [lathe](#) [steady](#)

When turning long very thin, a string steady rest mounted to the tail stock is essential. This model is designed to mount to a #2 Morse Taper arbor such as https://littlemachineshop.com/products/product_view.php?ProductID=1613&category=

In use, waxed string is wrapped around the spindle and around each screw.

For an in use example, please see:

<https://www.aswoodturns.com/2024/06/trembling-trembleur/>

Model files



stringsteady.stl

License

This work is licensed under a
[Creative Commons \(4.0 International License\)](#)



Attribution-NonCommercial

-
- ✗ | Sharing without ATTRIBUTION
 - ✓ | Remix Culture allowed
 - ✗ | Commercial Use
 - ✗ | Free Cultural Works
 - ✗ | Meets Open Definition