



## Ender 3 extruder mount for cable chain

a ali1234

VIEW IN BROWSER

updated 20. 6. 2024 | published 20. 6. 2024

### Summary

This is a clip to attach the johnniewhiskey cable chain (<https://www.thingiverse.com/thing:2920060>) to the X gantry....

[3D Printers](#) > [Accessories](#)

Tags: [thingiverse](#)

This is a clip to attach the johnniewhiskey cable chain (<https://www.thingiverse.com/thing:2920060>) to the X gantry. Many other brackets are available for this purpose, but mine is different. It is very easy to fit - you just clip it around the extruder stepper, attach the cable chain, and zip tie the X cable where it exits the channel. No need to disassemble the extruder or the Z rod. This also has the benefit of leaving the other commonly used attachment methods free for filament guides etc. It also doesn't need any supports to print.

Update: I have added a tweaked version as the original bent out of shape after a while. It is stronger but you have to remove the stepper to fit it. You might also need to clip a bit off the last chain link to make it fit.

### Print Settings

**Printer Brand:**

Creality

**Printer:**

Ender 3

**Rafts:**

No

**Supports:**

No

**Resolution:**

0.12mm

**Infill:**

20%

**Filament:** eSun PLA+

Peak Green

Category: 3D Printer Accessories

## Model files



**nemaclipv2-14mm.stl**



**nemaclipv2-18mm.stl**



**nemaclipv2-22mm.stl**

**nemaclip.scad**

nemaclipv2.scad

[Find source .stl files on Thingiverse.com](#)

## License



This work is licensed under a  
**Creative Commons (4.0 International License)**

**Attribution-ShareAlike**

- 
- ✗ | Sharing without ATTRIBUTION
  - ✓ | Remix Culture allowed
  - ✓ | Commercial Use
  - ✓ | Free Cultural Works
  - ✓ | Meets Open Definition