



## Sovol SV08 Screw fix Powersupply cover

**B** **Blaubartking**

[VIEW IN BROWSER](#)

updated 16. 7. 2024 | published 16. 7. 2024

### Summary

Power supply cover broken screw fix.

[3D Printers](#) > [Other Printer Parts & Upgrades](#)

Tags: **sv08**

I had a problem with the screws of the power supply support cover. These were unfortunately broken during shipping or from the factory, and as a result, the cover was no longer secure. Therefore, I designed a small file that solves this problem by allowing the screws to be reattached. Simply snap it on, preferably glue it in place, and screw it back in. Issue solved.

**Warning Do not touch high voltage parts. Do this at your own risk. Pay attention to your safety. Always pull the plug.**

### Model files



**sv08-screw-fix.stl**

☐ you will need up to four

# License ©

This work is licensed under a  
**Creative Commons (4.0 International License)**



## Attribution

---

- ✗ | Sharing without ATTRIBUTION
- ✓ | Remix Culture allowed
- ✓ | Commercial Use
- ✓ | Free Cultural Works
- ✓ | Meets Open Definition