



Ender 3 S1 Filament guide

B Ben090

[VIEW IN BROWSER](#)

updated 27. 7. 2024 | published 27. 7. 2024

Summary

Simple filament guide for the Ender 3 S1

[3D Printers](#) > [Creality Parts & Upgrades](#)

Tags: [drybox](#) [filament](#) [filamentguide](#) [2020extrusion](#)

Simple Filament guide for Ender 3 S1

- 2x M5x10
- 1x M5x20
- 1x M5 Nut
- 2x M5 T-Nut
- 2x Bearing 625zz

The bearings are from a Creality POM wheel and the T nuts and the M5x10 screws are included with the printer. This is the first version! A mount for the filament runout sensor is in progress.

Model files



bracket.stl

|| V1



washerm5.stl

|| V1



wheel.stl

|| V1.1

License Θ



This work is licensed under a
[Creative Commons \(4.0 International License\)](#)

[Attribution—Noncommercial—No Derivatives](#)

-
- ✖ | Sharing without ATTRIBUTION
 - ✖ | Remix Culture allowed
 - ✖ | Commercial Use
 - ✖ | Free Cultural Works
 - ✖ | Meets Open Definition