



Qidi Heat Bed Cable Support

 Elphwrkz

[VIEW IN BROWSER](#)

updated 1. 5. 2022 | published 29. 3. 2022

Summary

The Qidi heat bed cable needs to be supported to avoid the solder joints failing and the cable falling off.

[3D Printers](#) > [3D Printers - Upgrades](#)

Tags: [cableholder](#) [qidi](#) [xmax](#) [xplus](#) [xcf](#)

This is a remix of a model available on Thingiverse.

<https://www.thingiverse.com/thing:4869017>

The one on Thingiverse would not fit my cable so I made the cable hole larger.

I made another version that is shorter which I prefer.

If you print high temperature filaments with the chamber closed then print this using PA12-CF or similar filament, otherwise enhanced PLA is fine.

Model files



heat-bed-cable-holder.stl

☐ No supports. Print orientation is as shown.



heat-bed-cable-holder-short.stl

☐ No supports. Print orientation is as shown.

[Find source .stl files on Thingiverse.com](#)

License

This work is licensed under a
Creative Commons (4.0 International License)



Attribution

-
- ✗ | Sharing without ATTRIBUTION
 - ✓ | Remix Culture allowed
 - ✓ | Commercial Use
 - ✓ | Free Cultural Works
 - ✓ | Meets Open Definition