



Prusa I3 MK3S Print fan Shroud with Support



Xoggy

[VIEW IN BROWSER](#)

updated 3. 6. 2020 | published 3. 6. 2020

Summary

So i hade a bit of problem with the print fan shroud starting to get soft and dropping down on the right side (that is...



0.93 hrs



1 pcs



0.15 mm



0.40 mm



PET



4 g



Prusa
MK3/S/S+

[3D Printers](#) > [3D Printers - Upgrades](#)

So i hade a bit of problem with the print fan shroud starting to get soft and dropping down on the right side (that is unsupported) when i was running print with huges first layers so the print fan was not on for a long time.

I grabed the STL from Prusa GitHub and added a little support on the right side.

Hope it helps you as well!

Print instructions

Print with support on the right for the "hook" (See Picture or use Gcode)

Only PETG, PLA will just melt.

Model files



fan-shroud-support.stl

Print files



prusa-i3-mk3s-fan-shroud_015mm_petg_mk3s_56m.gcode

🌀 PET 📏 0.40 mm 📏 0.15 mm ⌚ 0.93 hrs 📊 4 g 🖨️ Prusa MK3/S/S+

[Find source .stl files on Thingiverse.com](#)

License ©



This work is licensed under a
Creative Commons (4.0 International License)

Attribution-ShareAlike

-
- ✗ | Sharing without ATTRIBUTION
 - ✓ | Remix Culture allowed
 - ✓ | Commercial Use
 - ✓ | Free Cultural Works
 - ✓ | Meets Open Definition