



Hoover FH51200 Replacement Idler Pulley



fox8091

[VIEW IN BROWSER](#)

updated 9. 10. 2023 | published 9. 10. 2023

Summary

Replacement idler pulley for a Hoover Dual Power Pro Carpet Cleaner (Model FH51200). Requires original bearing and shaft

[Household](#) > [Other House Equipment](#)

Tags: [replacement](#) [repair](#)

This is a replacement for the idler pulley on the Hoover Dual Power Pro Carpet Cleaner. This part requires the bearing and shaft to be harvested from the original pulley.

Print Tips

Avoid PLA or PETG as the print material, as neither one can hold up to the temperatures required during operation. I personally had success using ABS. This model can print entirely without supports.

Model files



belt-tensioner-pulley.stl



belt-tensioner-pulley.step

License ©

This work is licensed under a
[Creative Commons \(4.0 International License\)](#)



Attribution

- ✗ | Sharing without ATTRIBUTION
- ✓ | Remix Culture allowed
- ✓ | Commercial Use
- ✓ | Free Cultural Works
- ✓ | Meets Open Definition