



## KLP1 WobbleX Module - Fix Z wobble

 Ixlolxl

[VIEW IN BROWSER](#)

updated 1. 4. 2024 | published 1. 4. 2024

### Summary

Use wobbleX to defeat the Z-wobble you encountered on KLP1!

[3D Printers](#) > [Other Printer Parts & Upgrades](#)

Tags: [zwobble](#) [thingiverse](#) [klp1](#) [kingroonklp1](#)

Your KLP1 has an ugly Z wobble? This is caused by the Z screws not being aligned and is very difficult to adjust on this machine.

Welcome to the ultimate solution, wobbleX. The prerequisite for using this printable part is that you have purchased the wobbleX WS8 version and have two extra M3X30 screws and four M3 heat inserts (M3X6X5 same as voron use).

!! The part with heat insert is screwed with hot bed. !!

Hats off to the developers of wobbleX for making 3D printing one step closer to people's lives.

The original developer page is here: <https://github.com/MirageC79/Interfaces-for-WobbleX-integration>

## Print Settings

### Printer Brand:

VoronDesign

### Printer:

Voron2 Custom

### Rafts:

No

### Supports:

No

### Resolution:

### Infill:

15%up

### Filament: **ABS**

Category: 3D Printer Parts

## Model files



**top.3mf**



**wobblews8\_printedadapter.3mf**



**bottom.3mf**

[Find source .stl files on Thingiverse.com](#)

# License

This work is licensed under a  
**Creative Commons (4.0 International License)**



**Attribution—Noncommercial—Share Alike**

---

- ✗ | Sharing without ATTRIBUTION
- ✓ | Remix Culture allowed
- ✗ | Commercial Use
- ✗ | Free Cultural Works
- ✗ | Meets Open Definition