



Replacement plates for Bergeon No 7230



SirGibihm

[VIEW IN BROWSER](#)

updated 2. 4. 2024 | published 2. 4. 2024

Summary


Broke one of your top plates for the Bergeon No 7230 pin pushing tool? Replace it!

[Hobby & Makers](#) > [Tools](#)

Tags: [replacement](#) [watchmaking](#) [bergeon](#) [watchrepair](#)
[7230](#)

The pin-pushing tool Bergeon No 7230 comes with two plates that help align the band of the watch with the pusher. For an unknown reason, one of these plates stamped with **J G** broke in storage without any mechanical stress on it. So I designed replacements for both the the slimmer **J G** plate and the slightly thicker **L** plate.

Model files



bergeon_7230_replacement_plate_gj.3mf

bergeon_7230_replacement_plate_l.f3d



bergeon_7230_replacement_plate_l.3mf

bergeon_7230_replacement_plate_gj.f3d

License

This work is licensed under a
[Creative Commons \(4.0 International License\)](#)



Attribution

- ✗ | Sharing without ATTRIBUTION
- ✓ | Remix Culture allowed
- ✓ | Commercial Use
- ✓ | Free Cultural Works
- ✓ | Meets Open Definition