



## Diamont-Painting Transporkästchen 30 Dosen

 **Oswin**

[VIEW IN BROWSER](#)

updated 16. 5. 2024 | published 16. 5. 2024

### Summary

Diamont-Painting Transporkästchen 30 Dosen man benötigt noch 6 Schrauben M3 x 35 mit Muttern

[3D Printers](#) > [Other Printer Parts & Upgrades](#)

Tags: [diamontpainting](#)

Kiste zum Transport der Diamont-Painting-Döschen incl. "Schiffchen" undt Stifte


### This remix is based on



**Rugged Box (Parametric)**

by Whity

# Model files



## diamont-painting-transportbox-unterteil.stl

☐ Löcher mit 3,1 mm Bohrer nachbohren (Schrauben M3 x 35 verwenden )



## diamont-painting-transportbox-laschen.stl

☐ 2 x Drucken Löcher mit 3,1 mm Bohrer nachbohren (Schrauben M3 x 35 verwenden )



## diamont-painting-transportbox-deckel.stl

☐ Löcher mit 3,1 mm Bohrer nachbohren (Schrauben M3 x 35 verwenden )

# License ©

This work is licensed under a  
[Creative Commons \(4.0 International License\)](#)



**Attribution—Noncommercial—Share Alike**

- ✗ | Sharing without ATTRIBUTION
- ✓ | Remix Culture allowed
- ✗ | Commercial Use
- ✗ | Free Cultural Works
- ✗ | Meets Open Definition