


3D MODEL ONLY



Creality K1 PSU Fan Duct

 **Grazhevskiy**[VIEW IN BROWSER](#)

updated 2. 7. 2024 | published 2. 7. 2024

Summary

Allows the power supply to take air completely from the outside.

[3D Printers](#) > [Creality Parts & Upgrades](#)

Tags: crealityk1

Allows the power supply to take air completely from the outside.

Consists of two parts:

1. One is printed in PETG (at least).
2. Another in TPU/TPE in vase mode with a line width of 0.6mm.

Mounting

The standard fan screws are used for mounting.

Do not remove all the screws at once - the fan will fall inside the PSU! I recommend removing one screw from the PSU and screwing the fan duct onto this screw. Repeat this operation with the second one. Used together with the bottom.

As you can see in the photo, I also cut out the grille and added dust filters.

Model files



k1_psu_fan_duct_part2.stl



k1_psu_fan_duct_part1.stl

k1_psu_fan_duct.f3d

License

This work is licensed under a
[Creative Commons \(4.0 International License\)](#)



Attribution-NonCommercial

-
- ✗ | Sharing without ATTRIBUTION
 - ✓ | Remix Culture allowed
 - ✗ | Commercial Use
 - ✗ | Free Cultural Works
 - ✗ | Meets Open Definition