



Replacement arm for MK8 block



SirZapsALot

[VIEW IN BROWSER](#)

updated 26. 7. 2024 | published 26. 7. 2024

Summary

MK8 arm with slightly better adjustability

[3D Printers](#) > [Other Printer Parts & Upgrades](#)

The spring of the MK8 block can be too tight even at the lowest tension. This arm allows lower tension.

It is compatible with existing MK8 hardware. No additional hardware needed.

Model files



mk8-arm.stl

mk8-arm.step

License Θ

This work is licensed under a
GNU



General Public License v2.0

- ✗ | Sharing without ATTRIBUTION
- ✓ | Remix Culture allowed
- ✓ | Commercial Use
- ✓ | Meets Open Definition
- i | Share under the same license