



## Balcony sunshade accessory



dpVUE

[VIEW IN BROWSER](#)

updated 28. 3. 2022 | published 28. 3. 2022

### Summary

Part to replace damaged Balcony sunshade accessory



1.49 hrs



1 pcs



0.20 mm



0.40 mm



PET



18 g



Prusa  
MK3/S/S+

[Household](#) > [Outdoor & Garden](#)

Tags: [balcony](#) [sunshade](#) [rollerblinds](#)

Balcony sunshade accessory. This part always fails due to UV light. The role of it is to secure the bar. Without this part, the bar may fall during wind storms.

### Model files



pergola-v1.stl

# Print files



## pergola-v1\_02mm\_petg\_mk3s\_1h29m.gcode

PET 0.40 mm 0.20 mm 1.49 hrs 18 g Prusa MK3/S/S+

## License



This work is licensed under a  
[Creative Commons \(4.0 International License\)](#)

**Attribution—Noncommercial—Share Alike**

- 
- ✗ | Sharing without ATTRIBUTION
  - ✓ | Remix Culture allowed
  - ✗ | Commercial Use
  - ✗ | Free Cultural Works
  - ✗ | Meets Open Definition