



Lucca Console Cup Holder - Bad service & design fixed!



MiniSumo

[VIEW IN BROWSER](#)

updated 12. 4. 2022 | published 28. 3. 2022

Summary

This has been inspired by Bad Service, Missing Components and Rubbish Design.... Problem Solved!

[Household](#) > [Living Room](#)

Tags: [cupholder](#) [sofa](#) [consolestand](#) [lucca](#)

This has been inspired by Bad Service, Missing Components and Rubbish Design.... Lucca Sofa from Sofology with a missing cup holder in the drop down center console - a gaping hole!

Delivery guy ran a mile rather than engage on what was missing, no response from help desk queries and hours on hold before hearing they don't know if they can get the missing part!!!

Then you click that even if supplied to fill the hole, they're rubbish for mugs!

So, this disc has a step that presses into the original hole. the recess on the top will help stop an standard or oversized mug from slipping around.

Print Settings

Printer:

Creality CR6 SE

Rafts:

No

Supports:

Yes

Resolution:

0.2

Infill:

20%

Filament:

FilaPrint rePLAy - recycled PLA

Black

Category: Organization

Model files

lucca_-_cup_holder3.stl



[Find source .stl files on Thingiverse.com](#)

License ©

This work is licensed under a
[Creative Commons \(4.0 International License\)](#)



Attribution

- ✘ | Sharing without ATTRIBUTION
- ✓ | Remix Culture allowed
- ✓ | Commercial Use
- ✓ | Free Cultural Works
- ✓ | Meets Open Definition