



## Mikrotik SFP+ broken hinge fix

 Arek

[VIEW IN BROWSER](#)

updated 13. 7. 2024 | published 13. 7. 2024

### Summary

Fixes broken release mechanism hinge on Mikrotik SFP+ module

[Gadgets](#) > [Computers](#)

Tags: [mikrotik](#) [sfp](#)

Hinge broke in release mechanism in my SPF+ module. This fixes that

Used M1.6x4.

Note that the fix adds a lot of bulkiness to sides of the module. It might be not possible to place such fixed module in middle between other SFP+ modules in a switch for example.

Fusion 360 source attached.

**Thank you for your support.** If you found the project helpful, please [buy me a coffee](#) and see you in the next projects.

# Model files



**mikrotik-sfp-fix.stl**

---

**microtik-sfp-fix-bracket.f3d**

## License

This work is licensed under a  
**Creative Commons (4.0 International License)**



**Attribution-ShareAlike**

- 
- ✗ | Sharing without ATTRIBUTION
  - ✓ | Remix Culture allowed
  - ✓ | Commercial Use
  - ✓ | Free Cultural Works
  - ✓ | Meets Open Definition