



Volvo 240 front grill lower tab/leg repair piece

 **tiblu**

[VIEW IN BROWSER](#)

updated 1. 7. 2023 | published 1. 7. 2023

Summary

Volvo 240 front grill lower tab/leg repair piece for outer tab/leg.

[Hobby & Makers](#) > [Automotive](#)

Tags: [volvo](#) [volvo240](#) [240](#) [grill](#)

Volvo 240 front grill lower tab/leg repair piece

Use:

- Print right (R) or (L) repair piece. R and L are from driver perspective that is if you look at the grill from radiator side. **NOTE:** Print on its "back", that is, slide-in slot facing up and supports under the tab/leg. This way the layer direction gives maximum strength and least amount of supports is required.
- Sand flat the broken leg/tab.
- Slide the print into it's pocket, making sure angled edge faces out.
- Drill a hole through the block and the grill.
- Screw in a retaining screw.

Originally designed for Volvo 245L Hearse (1978).

All questions and feedback welcome!
All modifications back to the community!

Model files



volvo-240-front-grille-lower-towel-repair-piece-r.3mf



volvo-240-front-grille-lower-towel-repair-piece-l.3mf

License

This work is licensed under a
[Creative Commons \(4.0 International License\)](https://creativecommons.org/licenses/by-nc-sa/4.0/)



Attribution—Noncommercial—Share Alike

-
- ✗ | Sharing without ATTRIBUTION
 - ✓ | Remix Culture allowed
 - ✗ | Commercial Use
 - ✗ | Free Cultural Works
 - ✗ | Meets Open Definition