



Ikea Vättern bathroom cabinet mirror cover

xorath

[VIEW IN BROWSER](#)

updated 8. 10. 2023 | published 8. 10. 2023

Summary

Ikea Vättern mirror covers do rust and loose their finish/color over the years, this is a print to replace them.

[Household](#) > [Bathroom](#)

Tags: [ikea](#) [mirror](#) [vattern](#)

Our bathroom Ikea Vättern cabinets are about 15 years old and the mirror covers are starting to fall apart in their finish. I designed a replacement part for them. Just unscrew the old part and reuse the screws to put the new printed part in the same place.

No supports required for screw holes.

I printed the ones in the photo with PETG and 0.25mm first layer and 0.2mm for the rest.

Model files

ikea-vattern-mirror-cover.3mf



ikea-vattern-mirror-cover.step

License

This work is licensed under a
[Creative Commons \(4.0 International License\)](#)



Attribution-ShareAlike

- ✗ | Sharing without ATTRIBUTION
- ✓ | Remix Culture allowed
- ✓ | Commercial Use
- ✓ | Free Cultural Works
- ✓ | Meets Open Definition